## **Amendments to the Specification**

Kindly insert the following replacement paragraph for the paragraph spanning Specification pages 26-27:

Figure 15 shows a side view of the housing 66. An example of a fraud device which comprises unauthorized card reading device 130 is shown attached externally to the housing 66. The unauthorized card reading device includes a slot 132 generally aligned with slot 28 128. The device 130 also includes a sensor shown schematically as 134 which is operative to sense the encoded magnetic flux reversals which represent data on the magnetic stripe of a credit or debit card. As can be appreciated, an arrangement of the type shown in Figure 15 enables the sensor 134 if properly aligned adjacent to the magnetic stripe of a card, to read the card data as the card passes in and out of slot 28 128. Such an unauthorized reading device may be connected via RF or through inconspicuous wiring to other devices which enable interception of the card data. In some situations criminals may also endeavor to observe the input of the user's PIN number corresponding to the card data so as to gain access to the account of the user.